



**Dominion**

# **DAM INSPECTION CHECKLIST** **POSSUM POINT POWER STATION** **POND ABC**

INSPECTION DATE: 3/31/15 1017 hrs.

WEATHER: Few clouds, 58°F

INSPECTED BY: D. West, K. Homza

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	Y*	Y*	1017 hrs. Standing water at perimeter of pond along road.
Erosion	N	N	8" deep standing water behind sandbags. Audible flow heard below rip rap.
Low Point, B dike*			
Flow	N	N	1020 hrs. Small area behind sandbags of standing
Erosion	N	N	water.
Outfall			
water surface El. (top of stoplogs to water)			1031 hrs. Standing water behind sandbags. No flow behind sandbags. 49 1/2". Standing water behind weir. Seeping into concrete weir structure.

\* See figure below.

**Additional Comments** (Note any changes observed along the embankment crest or downstream slope observed from the crest.): \* No visible flow observed, only audible below rip rap. water in road cuts.

Low 1100 High 1728

